



Scaffolding externally
Straightening & re plastering to sunshades
Fence (boundary wall)-on progress



Covered walkway
Steel column well erected
Re plastered round column at the main entrance

